

**Hydrant Inspection Report****Docket No. 97-0606****ICC Staff Ex. 3.00****Schedule 3.03, pg. 1 of 2****Highland Shores Water Company**

	Static	Flow	Gals.	Minutes	
Location	Pressure	Pressure	per minute	Flowed	Comments
Wellhouse on Memory Trail					a) Replace - leaking
Between Vine Ave. & Oriole Trail	60	5	340	12	
on Pleasure Lane					
Between Evergreen & Oriole Trail	78	15	630	7	a) Increase height of hydrant (18" to middle of Cap)
on Thompson					b) Hydrants requires painting;
Between Evergreen & Pine	60	5	425	5	a) Hydrant requires painting;
on Meadow Lane					
Memory & Meadow	47	30	935	7	a) Hydrant requires painting;
Between Shady & Sunset	40	22	770	15	a) Hydrant requires painting;
on Meadow Lane					
Between Acorn & Ramble	40	3	400	4	a) Hydrants requires painting;
on Meadow Lane					
Between Highland & Woody	40	5	340	5	a) Replace - upper barrel crack.
on Meadow Lane					
Thompson & Acorn	43	8	530	2	a) Hydrants requires painting;
Between Ramble & Sunset	45	20	770	8	a) Hydrants requires painting;
on Thompson					

**Hydrant Inspection Report****Docket No. 97-0606****ICC Staff Ex. 3.00****Schedule 3.03, pg. 2 of 2****L**

Static	Flow	Gals.	Minutes	
Pressure	Pressure	per minute	Flowed	Comments
60	25	830	8	
70	20	730	23	a) Replace - upper barrel crack.
75	20	670	7	a) Hydrant requires painting;
83	60	750	7	a) Hydrant requires painting;
83	40	750	10	a) Hydrant requires painting;
				a) Replace - Not operatable
		340	7	a) Install flushing hydrants.
		340	5	a) Install flushing hydrants.
		340	5	a) Install flushing hydrants.
		370	3	